

# Oil Field Environmental Incident Summary

**Incident:** 20170620172145      **Date/Time of Notice:** 06/20/2017 17:21

**Responsible Party:** FOUNDATION ENERGY MANAGEMENT, LLC

**Well Operator:** FOUNDATION ENERGY MANAGEMENT, LLC

**Well Name:** LYNNE 34-2

**Field Name:** WABEK

**Well File #:** 12233

**Date Incident:** 6/20/2017

**Time Incident:** 06:30

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 152

**Rng:** 88

**Sec:** 2

**Qtr:**

**Location Description:**

**Submitted By:** Tishany Jenkins

**Received By:**

**Contact Person:** Tishany Jenkins  
16000 DALLAS PARKWAY, STE 875  
DALLAS, TX 75248

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	80	Barrels			80	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 8/4/2017

**Clean Up Concluded:** 6/22/2017

**Risk Evaluation:**

n/a

**Areal Extent:**

**Potential Environmental Impacts:**

n/a

**Action Taken or Planned:**

A vac truck and freshwater truck were sent to the location to suck up as much free water as possible and to clean up any additional salty water and oil with freshwater. We may have to get a hydrovac to remove contaminated soil due to the brine water.

***Wastes Disposal Location:***

***Agencies Involved:***

### ***Updates***

---

***Date:*** 6/21/2017    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Stockdill, Scott

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

According to the incident summary this spill remained on location. NDIC retains oversight.